CLASSIFICATION SECOUNTRY East Germany Forchim Airfield	REPORT	NO		**
			Cort Allanck to the Community (Spec) All throwing and about continuous regularization	The state of the s
	1			25X
DATE OF CONTENT.	March Mar (M. C. C.) (Mar Piller Stat. 1995) Milliply and reduce 1994 in All Co. L. Calaparic, September 4, Mary Statistics			The districts
DATE OBTAINED	DATE PREPARED	9 Sept	ember 1953	N. Constitution of the Con
INLITEINGNOES			The state of the s	
PAGES ENCLOSURES (NO. & TYPE)		The state of the s		***************************************
REMARKS				-
AND	(Mediala	- The Control of the	K-1400-ber melepakan di angelogi a men atabbahan	COLUMN TO THE PERSON NAMED IN
	-	T. ST. AMERICAN ST. A. C. PROPERTON OF	No times and discours and replacement of the second	*
25X1	anderen der verber 1985 eine Geben der verber der Eren Stade verber der verber der der verber verber verber der der der der der der der der der d	U-Commission	Addition and a second that The Second showing with a second	
A CONTRACTOR OF THE CONTRACTOR OF THE PROPERTY OF THE CONTRACTOR O	AND AND ADDRESS OF THE PARTY OF			

- 1. On 18 July 1953, the Soviet construction headquarters at Werder again revised the plans for the aircraft revenments at Parchim sirfield. The Soviets ordered that only the 12 eastern reverments be completed, while all work on the remaining 28 reverments had to be suspended. The surplus earth resulting from the construction of the connecting lanes and the widening of the taxiway was to be used for the leveling of the field. Senior Lieutenant Lienyakov (fnu) ordered that the estimated cost for the 12 aircraft revenments to be built would to be submitted in two sections, one covering the cost for the concrete surface, the other far the protecting walls.
- 2. On 18 July, Senior Lieutenant Lisnyakov in Werder signed new plans, which related to the requirements of concrete for the runway at the airfield. The plans represent a correction in the previous plans, necessary because during the course of construction work it was discovered that the leveling reference points and the terrain had been determined inaccurately. On these plans the four-digit numbers in parentheses represent the height of the old runway over the height of the four-digit figures above the figures in parentheses represent the height of the new runway surface. The figure to the left of these two groups of figures represent the quantity of new concrete required in cubic meters.

25X1

Comments Of the 40 aircraft revetments originally scheduled to be built at Farchim airfield only 12 will be built for the time being probably for economic reasons. Sanior Lieutenant Lisnyakov is reported for the first time. For physographs of records related to the concrete requirements for the runway, see Annex, attachment. 2 sets of construction plans of Parchim airfield. (Air)

CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY